

**CITY OF FREDERICKSBURG
HISTORIC REVIEW BOARD**

Tuesday, August 12, 2014

City Hall

Conference Room

126 W. Main St.

5:30 P.M.

1. Call to Order
2. Approve Minutes of July 2014 Regular Meeting *Pp 1 - 2*

APPLICATIONS

3. Application #14-53 by Rick Hartmann on behalf of Zion Lutheran Church to remove three non-functioning chimneys at 415 W. Austin *Pp 3 - 8*
4. Application #14-54 by David and Gwen Fullbrook at 312 E. Travis to move 12' x 20' cabin to rear of structure and connect to existing deck *Pp 9 - 17*
5. Application #14-55 by Angela Moga at 313 W. Austin to install a two car, 20' x 21' carport *Pp 18 - 23*
6. Application #14-58 by H & H Vinyl Fencing on behalf of Melvin and DeLana Littleton to replace approximately 215 linear foot of wood privacy fence with simulated stone vinyl fencing at 202 S. Bowie *Pp 24 - 31*
7. Application #14-63 by Laughlin Homes & Restoration on behalf of Dr. John & Suzanne Shore at 522 W. Austin to construct a 5,655 square foot addition to existing structure *Pp 32 - 41*

DISCUSSIONS

8. Old Methodist Episcopal Church – 600 E. Main Street
9. 107 N. Orange – removal of architectural detail

SIGN OFF APPLICATIONS

10. #14-56 – Install fence on east side and rear – 209 E. Creek (Defazio)
11. #14-57 – Replace entry steps, add ramps and paint exterior – 108 N. Edison (Stotz)
12. #14-59 – Convert existing carport to porch & add covered walkway – 1004 N. Llano (Padgett)
13. #14-60 – Add folding glass panels to interior face of courtyard arbor – 305 W. Main (Klenzing)
14. #14-61 – Replace fence – 508 W. San Antonio (Shelton)
15. #14-62 – Add fence in front of building & reinstall door – 203 E. San Antonio (August E's)
16. #14-64 – Replace roof and add gable dormer on front – 110 S. Acorn (Gentry)
17. #14-65 – Replace sash windows with transom windows – 103 E. Creek (Floyd)

ADJOURN

STATE OF TEXAS
COUNTY OF GILLESPIE
CITY OF FREDERICKSBURG

HISTORIC REVIEW BOARD
July 15, 2014
5:30 PM

On this 15th day of July, 2014 the Historic Review Board convened in regular session at the regular meeting place thereof, with the following members present to constitute a quorum:

SHARON JOSEPH
STAN KLEIN
KAREN OESTREICH
CHARLES SCHMIDT
ERIC PARKER
DAVID BULLION

ABSENT: MIKE PENICK
LARRY JACKSON

ALSO PRESENT: BRIAN JORDAN – Director of Development Services
PAT MCGOWAN – City Attorney
KYLE STAUDT - Building Official

The meeting was called to order at 5:30 PM by Sharon Joseph.

MINUTES

Eric Parker moved to approve the minutes from the June 2014 regular meeting. David Bullion seconded the motion. All voted in favor and the motion carried.

APPLICATIONS

Application #14-51 by Arthur Campos on behalf of Bill and Patty Sutherland to construct a new home on vacant lot at 212 E. Schubert – Arthur Campos, architect for the project, presented the application and stated the project will be a two story house, approximately 3000 square feet, wood construction with stone exterior and stucco on the rear. Mr. Campos noted the stone walls will define two courtyards, one on the south and one on the north. Mr. Campos presented elevation drawings of the proposed house and noted the street is lower than the lot so the house will sit higher than street level and the garage will be setback approximately 50 feet. Mr. Campos noted there will be a balcony off the studio above the garage that will be made from cable reel material. Mr. Campos noted the house will sit beyond the stone walls that make up the courtyard on the N. Lincoln side and stated the structure will be simple and familiar to Fredericksburg and added they are not trying to create a false sense of history.

Sharon Joseph noted she would like to see how the house fits in the neighborhood. Kyle Staudt, Building Official, showed street elevations of the surrounding properties. Bill Sutherland, owner

of the property, described the houses in the neighborhood and the direction the structures face. Mr. Sutherland noted the proposed house will have simple, clean lines with a Texas look that they believe will fit into Fredericksburg. Mr. Sutherland noted the exterior walls along the front property line will be four feet high and the walls on the sides of the house will be eight feet high. David Bullion noted the powerpoint presentation shows the side walls to be eleven feet high and Mr. Campos noted those will be brought down to eight feet. Stan Klein asked if a topographical survey would be done and Mr. Campos noted there would be one done. Mr. Klein noted the elevations will have some impact on the drawings and some adjustments may have to be made before the final approval will be granted. Mr. Campos noted he understands the approval would be conditioned upon certain items. There followed more discussion about the grade of the lot and Mr. Sutherland stated they would adjust the walls around the property line depending on the grade. Mr. Klein noted his concern is that the drawings do not represent the conditions of the lot and while he believes it will be a great compliment to the neighborhood, he would like to see a drawing that represents the true elevation. There followed much discussion about the height of the walls on the perimeter of the property. Sharon Joseph noted the scale of construction needs to be addressed because that is a responsibility of the Board. Mr. Klein noted the finished floor still needs to be established and the grades determined so the Board can get a true perspective of the project. From a building standpoint, Mr. Klein commented the house seems to be a project with contemporary interpretations that blends with the neighborhood. Mr. Klein noted his concerns with this project are the trees that could be lost during construction and not knowing the grade elevation. David Bullion noted the overall scale seems to fit in well with the neighborhood and the materials complement the houses across the street. There then followed discussion on how the measurement of height is calculated and Mr. Jordan explained how it is determined for building codes.

David Bullion moved to approve the design of the house presented on Application #14-51 with the exception of limiting the rock wall on the side streets, Schubert and Lincoln, to four feet high from the grade level of the house. Eric Parker seconded the motion. Mr. Klein noted during the due diligence process the applicants may find there is something else they didn't consider on the wall and if so, the Board is open to further evaluation. Mr. Bullion noted the Board is enforcing stricter restrictions than the City imposes in their zoning ordinance. All voted in favor and the motion carried.

Karen Oestreich thanked Mr. Jordan for his work in getting the wayfinding signs installed because she believes it adds a lot to the community.

ADJOURN

With nothing further to come before the Board, Larry Jackson moved to adjourn. Charles Schmidt seconded the motion. All voted in favor and the meeting was adjourned at 6:35 p.m.

PASSED AND APPROVED this the 14th day of August, 2014.

SHELLEY BRITTON, CITY SECRETARY

SHARON JOSEPH, CHAIRMAN

**Historic Review Board
Application Information**

Application Number: 14-53
Date: August 8, 2014
Address: 415 W. Austin
Owner: Zion Lutheran Church
Applicant: Rick Hartmann
Rating: Medium
Proposed Modifications: Chimney removal.
Neighborhood Characteristics: The subject property is in the Historic District.
Staff Comments: The scope of the project justifies Board review.

General Notes:

The mandatory functions of the Board include the following:

(1) Removal, addition or modification of architectural detail. The distinguishing historic qualities or character of a building, structure, or site and its environment shall not be destroyed. Removal or modification of any historic material or distinctive architectural features may be accomplished upon issue of certificate of appropriateness; however, this should be avoided when possible. Architectural features include but are not limited to exterior wall materials, windows, railings, decorative woodwork, masonry, or stone elements.

(2) Paint color and application. Traditionally, the base colors of Fredericksburg's buildings have been soft muted shades of greens, blues, whites, and tans. In order to continue the historic integrity of the buildings in the district, these colors continue to be acceptable today, and do not require review or issuance of a certificate. The building official shall determine whether or not the proposed color is within the approved list of colors. Base colors such as vibrant or "hot" shades, dark deep shades, and black shades are not acceptable. If one wishes to use these colors, a certificate of appropriateness must be granted in advance of paint application. The painting of existing historic buildings composed of materials such as unpainted stone or unpainted masonry is prohibited.

(3) New construction in historic districts. The board will review all new construction plans within Historic Districts in order to ensure visual compatibility with the surrounding buildings and environment in relation to height, gross volume, proportion, design harmony and setback.

The advisory functions of the Board include the following:

- (1) The effect of the proposed change on the general historic, cultural, and architectural nature of the historic district or landmark.
- (2) The appropriateness of exterior architectural features which can be seen from a public street, alley, or walkway.
- (3) The general design, arrangement, texture, color, and material of the building, or structure, and the relation of such factors to similar features of buildings, or structures, in the district. This consideration shall not be the aesthetic appeal of the structure to the board nor the proposed remodeling, but rather its conformity to the general character of the particular historic area involved.
- (4) Conformance of signage to the general historic, cultural, and architectural character of the historic district or landmark.
- (5) The effects of the proposed change to the value of the historic district or landmark as an area of unique interest and character.
- (6) The general and specific Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, as issued by the secretary of the interior.
- (7) The importance of finding a way to meet the current needs of the property owner and the importance of approving plans that will be economically reasonable for the property owner to carry out.

Preservation Priority Rating. Three-tier rating system used in the 2002 *Fredericksburg Historic Resource Survey* to evaluate all properties within, and adjoining to, the City's Historic District. Ratings are based upon current determinations of architectural value and integrity and, if known, historical and cultural value, and may be altered from time to time as additional information is discovered or circumstances change.

HIGH rating. The most significant properties identified in the 2002 *Fredericksburg Historic Resource Survey*. These properties are considered to be outstanding, unique, or good examples of architecture, engineering, or design. Some are unique to the Fredericksburg area and are indicative of German-Texan vernacular forms and/or building techniques. Others are noteworthy examples of 19th and early 20th century architectural types, styles, and forms, erected using local building materials and construction technologies. Properties designated with a high rating are to be the most protected from alteration and demolition.

MEDIUM rating. Properties that may or may not be identified as architecturally significant on an individual basis, but are nonetheless valuable resources that add to the Historic District's overall character, and may be so ranked due to their or its proximity or contribution to the cultural, historic, architectural, or archeological character of the Historic District or surrounding properties. These properties may have been moderately altered or are typical examples of a common architectural style or form, but generally retain their historic integrity to a good or moderate degree. Properties designated with a medium rating shall be protected from demolition and where possible will be required or encouraged to maintain or improve architectural features.

LOW rating. Properties that minimally enhance the district's ability to convey a sense of time and place. These properties may be typical examples of more recent, common local building forms, architectural styles, or plan types; be examples of distinctive building forms, architectural styles, or plan types that have been significantly altered; lack the necessary age to meet the usual fifty (50) year threshold for possible National Register of Historic Places listing and do not appear to meet the National Register of Historic Places standard for exceptional significance for properties less than fifty (50) years of age, but which nevertheless may have relative value within the Historic District, meriting preservation. Properties or improvements with a low rating may be considered for relocation or demolition upon a determination by the Historic Review Board that the same can be accomplished with little or no consequence to the historical, cultural, architectural, or archeological character of the district or property.

Application for Certificate of Appropriateness

Application Date: July 3, 2014 Application Complete: July 3, 2014

Property Address: 415 W. AUSTIN ST. FBG, TX 78624

Owner: Zion Lutheran Church Phone No. 830-997-2195

Address: 415 W. AUSTIN ST, FBG, TX 78624

Applicant: Rick Hartmann, pastor Phone No. 830-383-9310

Address: 424 W. MAIN ST. FBG, TX 78624 Fax No. 830-997-9835

Description of External Alteration/Repair or Demolition: There are 3 non-working chimneys on the roof, 2 on the west side, one on the peak of the east side (harder to see in the picture). They are dangerous & need to be removed.

Description of how the proposed change will be in character with the architectural or historic aspect of the structure or site: We could perhaps leave the one on the south west side, but from the enclosed picture the integrity of the house remains intact.

Any circumstances or conditions concerning the property which may affect compliance with the ordinance: _____

Unaware / not sure

Photos Drawing Sketch Date Submitted: July 7, 2014 Historic Photograph

Desired Starting Date: July 25, 2014 Desired Completion Date: 8/15/2014

SURVEY RATING: High Medium Low None

RTHH: Estimated Date of Construction _____

APPLICANT SIGNATURE: [Signature]


The Applicant certifies that he/she is the Owner or duly authorized Agent for the Owner of the Property

Building Official's Determination Date _____ Insignificant Significant (Max 7 days)

[Signature]
Chairman's Determination Date 7/15/14 Insignificant Significant (Max 7 days)

Meeting Date (40 days max. after complete application) _____ Notice to Applicant: _____

APPLICATION FEE: -\$10.00 plus Board Review; CERTIFICATE OF APPROPRIATENESS -\$20.00



Note are
Solidly placed -
No infrastructure there
to hold them.





Image after
removed.



Inventory of Properties

409 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 148
 Address 409 W. Austin
 Date 1920
 Stylistic Influence Craftsman
 GCAD Hyperlink [R1285](#)
 Owner ZION EVANGELICAL LUTHERAN CHURCH
 Historic District Yes Historic District
 Assessment Outstanding example of a unique building plan that displays distinctive stylistic features and retains original materials. Outstanding decorative features contribute to the resource's significance.

Notes

1983 Historic Resources Survey	
Previous Site No.	87
Previous Ranking	3
Previous Photo References	
Roll	18
Frame	32

412 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 57
 Address 412 W. Austin
 Date 1890
 Stylistic Influence vernacular
 GCAD Hyperlink [R23492](#)
 Owner SCHLIETER, ROBERT A & PATRICIA
 Historic District Yes Historic District
 Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes

1983 Historic Resources Survey	
Previous Site No.	88
Previous Ranking	2
Previous Photo References	
Roll	24 24
Frame	30 31

414 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 56
 Address 414 W. Austin
 Date 1865
 Stylistic Influence vernacular
 GCAD Hyperlink [R25175](#)
 Owner GRAHAM, JOHN JR ETUX
 Historic District Yes Historic District
 Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes Strackbein-Roeder Home.

1983 Historic Resources Survey	
Previous Site No.	89
Previous Ranking	1
Previous Photo References	
Roll	24 24 24
Frame	26 37 28

207 S. Columbus



2002-05 Re-evaluation

High Medium Low

Site ID No. 1032
 Address 207 S. Columbus
 Date 1915
 Stylistic Influence vernacular
 GCAD Hyperlink [R22440](#)
 Owner BURNETTE, NANCY S
 Historic District No Outside Historic District
 Assessment Example of a distinctive building type or architectural style that has suffered severe alterations or deterioration, resulting in a loss of historical integrity.

Notes addition; siding changes

1983 Historic Resources Survey	
Previous Site No.	90
Previous Ranking	2
Previous Photo References	
Roll	18 18
Frame	33 34

415 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 147
 Address 415 W. Austin
 Date 1870
 Stylistic Influence vernacular
 GCAD Hyperlink [R2613](#)
 Owner ZION LUTHERAN CHURCH
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has undergone alterations or deterioration. Despite alterations or deterioration, resource retains much of its original form and character. Outstanding decorative features contribute to the resource's significance.

Notes Recent addition at rear

1983 Historic Resources Survey	
Previous Site No.	90
Previous Ranking	2
Previous Photo References	
Roll	18 18
Frame	33 34

the 1990s, the number of people in the UK who are aged 65 and over has increased from 10.5 million to 13.5 million, and the number of people aged 75 and over has increased from 4.5 million to 6.5 million (Office for National Statistics 2000). The number of people aged 65 and over is projected to increase to 17.5 million by 2020, and the number of people aged 75 and over to 8.5 million (Office for National Statistics 2000).

There is a growing awareness of the need to address the needs of older people, and the need to ensure that they are able to live independently and actively in their own homes. This has led to a number of initiatives, including the development of the National Framework for Older People (Department of Health 1999) and the National Strategy for Older People (Department of Health 2000). The National Framework for Older People sets out the government's commitment to older people, and the National Strategy for Older People sets out the government's strategy for addressing the needs of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

The National Framework for Older People and the National Strategy for Older People are both important documents that set out the government's commitment to older people. They provide a clear framework for the development of policies and services for older people, and they provide a clear focus for the work of the government and its agencies. They are both essential documents for anyone who is involved in the care of older people.

**Historic Review Board
Application Information**

Application Number: 14-54

Date: August 8, 2014

Address: 312 E. Travis

Owner: David and Gwen Fullbrook

Applicant: Gwen Fullbrook

Rating: High

Proposed Modifications: See attached.

Neighborhood Characteristics: The subject property is in the Historic District.

Staff Comments: The scope of the project justifies Board review.

General Notes:

The mandatory functions of the Board include the following:

- (1) Removal, addition or modification of architectural detail.** The distinguishing historic qualities or character of a building, structure, or site and its environment shall not be destroyed. Removal or modification of any historic material or distinctive architectural features may be accomplished upon issue of certificate of appropriateness; however, this should be avoided when possible. Architectural features include but are not limited to exterior wall materials, windows, railings, decorative woodwork, masonry, or stone elements.
- (2) Paint color and application.** Traditionally, the base colors of Fredericksburg's buildings have been soft muted shades of greens, blues, whites, and tans. In order to continue the historic integrity of the buildings in the district, these colors continue to be acceptable today, and do not require review or issuance of a certificate. The building official shall determine whether or not the proposed color is within the approved list of colors. Base colors such as vibrant or "hot" shades, dark deep shades, and black shades are not acceptable. If one wishes to use these colors, a certificate of appropriateness must be granted in advance of paint application. The painting of existing historic buildings composed of materials such as unpainted stone or unpainted masonry is prohibited.
- (3) New construction in historic districts.** The board will review all new construction plans within Historic Districts in order to ensure visual compatibility with the surrounding buildings and environment in relation to height, gross volume, proportion, design harmony and setback.

The advisory functions of the Board include the following:

- (1) The effect of the proposed change on the general historic, cultural, and architectural nature of the historic district or landmark.
- (2) The appropriateness of exterior architectural features which can be seen from a public street, alley, or walkway.
- (3) The general design, arrangement, texture, color, and material of the building, or structure, and the relation of such factors to similar features of buildings, or structures, in the district. This consideration shall not be the aesthetic appeal of the structure to the board nor the proposed remodeling, but rather its conformity to the general character of the particular historic area involved.
- (4) Conformance of signage to the general historic, cultural, and architectural character of the historic district or landmark.
- (5) The effects of the proposed change to the value of the historic district or landmark as an area of unique interest and character.
- (6) The general and specific Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, as issued by the secretary of the interior.
- (7) The importance of finding a way to meet the current needs of the property owner and the importance of approving plans that will be economically reasonable for the property owner to carry out.

Preservation Priority Rating. Three-tier rating system used in the 2002 *Fredericksburg Historic Resource Survey* to evaluate all properties within, and adjoining to, the City's Historic District. Ratings are based upon current determinations of architectural value and integrity and, if known, historical and cultural value, and may be altered from time to time as additional information is discovered or circumstances change.

HIGH rating. The most significant properties identified in the 2002 *Fredericksburg Historic Resource Survey*. These properties are considered to be outstanding, unique, or good examples of architecture, engineering, or design. Some are unique to the Fredericksburg area and are indicative of German-Texan vernacular forms and/or building techniques. Others are noteworthy examples of 19th and early 20th century architectural types, styles, and forms, erected using local building materials and construction technologies. Properties designated with a high rating are to be the most protected from alteration and demolition.

MEDIUM rating. Properties that may or may not be identified as architecturally significant on an individual basis, but are nonetheless valuable resources that add to the Historic District's overall character, and may be so ranked due to their or its proximity or contribution to the cultural, historic, architectural, or archeological character of the Historic District or surrounding properties. These properties may have been moderately altered or are typical examples of a common architectural style or form, but generally retain their historic integrity to a good or moderate degree. Properties designated with a medium rating shall be protected from demolition and where possible will be required or encouraged to maintain or improve architectural features.

LOW rating. Properties that minimally enhance the district's ability to convey a sense of time and place. These properties may be typical examples of more recent, common local building forms, architectural styles, or plan types; be examples of distinctive building forms, architectural styles, or plan types that have been significantly altered; lack the necessary age to meet the usual fifty (50) year threshold for possible National Register of Historic Places listing and do not appear to meet the National Register of Historic Places standard for exceptional significance for properties less than fifty (50) years of age, but which nevertheless may have relative value within the Historic District, meriting preservation. Properties or improvements with a low rating may be considered for relocation or demolition upon a determination by the Historic Review Board that the same can be accomplished with little or no consequence to the historical, cultural, architectural, or archeological character of the district or property.

14-54

Application for Certificate of Appropriateness

Application Date: 7-7-14 Application Complete: _____

Property Address: 312 E. TRAVIS

Owner: DAVIS OWEN Fullbrook Phone No. (830) 997-3613

Address: 312 E. TRAVIS

Applicant: OWEN Fullbrook Phone No. 456-2623 cell

Address: SAME Fax No. 997-9211 ofr

Description of External Alteration/Repair or Demolition: _____

Move in 12x20 Cabin to be connected to back deck.
Exterior will be painted to match house

Description of how the proposed change will be in character with the architectural or historic aspect of the structure or site: _____

Building is wood siding, front porch, and tin roof.
Will be painted to match main house.

Any circumstances or conditions concerning the property which may affect compliance with the ordinance: _____

Drawing Sketch Date Submitted: _____ Historic Photograph

Desired Starting Date: ASAP Desired Completion Date: 2 weeks

SURVEY RATING: High Medium Low None
 RPHL: Estimated Date of Construction _____

APPLICANT SIGNATURE: [Signature]

The Applicant certifies that he/she is the Owner or duly authorized Agent for the Owner of the Property

[Signature] Date 7/7/14 Insignificant Significant
Building Official's Determination (Max 7 days)

[Signature] Date _____ Insignificant Significant
Chairman's Determination (Max 7 days)

Meeting Date (40 days max. after complete application) _____ Notice to Applicant: _____

APPLICATION FEE: -\$10.00 plus Board Review; CERTIFICATE OF APPROPRIATENESS-\$40.00

~~Withdrawn~~

~~8/14~~
||


RECEIVED
JUL 07 2014

LOT 3
DILTZ SUBDIVISION
VOLUME 2, PAGE 120
PLAT RECORDS

0.331 ACRES

MARK B. McMURREY AND
CECILIA JOHNSON McMURREY
0.29 ACRES
VOLUME 601, PAGE 363
OFFICIAL PUBLIC RECORDS

Scale: 1" = 30'



- LEGEND**
- ☐ MAILBOX
 - ☐ ELECTRIC METER
 - ☐ WATER METER
 - ☐ GAS METER
 - ☐ TELEPHONE PEDASTAL
 - ☐ CABLE TV PEDASTAL
 - ☐ SEWER MANHOLE
 - ☐ POWER POLE
 - GUY WIRE
 - WOOD FENCE
 - WIRE FENCE
 - OVERHEAD ELECTRIC
 - OHT- OVERHEAD TELEPHONE
 - CATV- OVERHEAD CABLE TV
 - EDGE OF PAVEMENT
 - POB POINT OF BEGINNING
 - ☐ FIRE HYDRANT



BORROWERS:
DAVID FULLBROOK AND GWEN FULLBROOK
I HEREBY CERTIFY THAT THIS SURVEY WAS MADE
IN ACCORDANCE WITH THE RULES AND REGULATIONS
REPRESENTING THE FACTS FOUND AT THE TIME OF
THIS SURVEY AND THAT THERE ARE NO VISIBLE
EXCEPTIONS OR ENCROACHMENTS OF IMPROVEMENTS
EXCEPT AS SHOWN HEREON.


[Signature]
DAVID FULLBROOK
REGISTERED PROFESSIONAL LAND SURVEYOR
5357
TEXAS REGISTRATION NO.

ADDRESS:
312 EAST TRAVIS STREET


NOTE:

- 1) BASIS OF BEARING WAS ESTABLISHED FROM THE STREET BEARING
SHOWN ON THE SURVEY. THE FOLLOWING REFERENCED DEED:
2) A RELIABLE DESCRIPTION OF THE ABOVE SHOWN TRACT WAS PREPARED.
- PLAT SHOWING: A 0.331 ACRE TRACT OF LAND
OUT OF OUT LOT NO. 274 AS SAID OUTLOT IS
SHOWN AND DESIGNATED ON THE MAP OF
FREDERICKSBURG, TEXAS AND ENVIRONS, BY THE
GERMAN EMIGRATION COMPANY, SAID 0.331 ACRE
TRACT OF LAND ALSO BEING THAT CERTAIN 0.33
ACRE TRACT OF LAND CONVEYED TO DAVID
FULLBROOK AND WIFE, GWEN FULLBROOK BY
DEED RECORDED IN DOCUMENT NO. 20066507,
OFFICIAL PUBLIC RECORDS, GILLESPIE COUNTY,
TEXAS.

HILL COUNTRY LAND SURVEYING, LLC
110 NORTH MILAM STREET
FREDERICKSBURG, TEXAS 78624
PHONE: (830) 990-2665



13





15



16

Inventory of Properties

309 E. Travis



2002-05 Re-evaluation

High Medium Low

Site ID No. 846
 Address 309 E. Travis
 Date 1990
 Stylistic Influence vernacular
 GCAD Hyperlink
 Owner
 Historic District Yes Potential Historic District

Assessment The resource's construction date fails to meet the age threshold for designation as a high or medium preservation priority.

Notes

1983 Historic Resources Survey

Previous Site No. 780

Previous Ranking 3

Previous Photo References

Roll

Frame

309 (side) E. Travis



2002-05 Re-evaluation

High Medium Low

Site ID No. 847
 Address 309 (side) E. Travis
 Date 1990
 Stylistic Influence
 GCAD Hyperlink [R27070](#)
 Owner JARREAU, JAMES W & DANITA J
 Historic District Yes Potential Historic District

Assessment The resource's construction date fails to meet the age threshold for designation as a high or medium preservation priority.

Notes

1983 Historic Resources Survey

Previous Site No. 780

Previous Ranking 3

Previous Photo References

Roll 31

Frame 18

310 E. Travis



2002-05 Re-evaluation

High Medium Low

Site ID No. 654
 Address 310 E. Travis
 Date 1900
 Stylistic Influence Queen Anne; Craftsman
 GCAD Hyperlink [R1678](#)
 Owner
 Historic District Yes Potential Historic District

Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes

1983 Historic Resources Survey

Previous Site No. 781

Previous Ranking 3

Previous Photo References

Roll 1

Frame 30

311 E. Travis



2002-05 Re-evaluation

High Medium Low

Site ID No. 845
 Address 311 E. Travis
 Date 1900
 Stylistic Influence vernacular
 GCAD Hyperlink [R22213](#)
 Owner
 Historic District Yes Potential Historic District

Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes Exterior wall materials and shed roof additions are historic alterations.

1983 Historic Resources Survey

Previous Site No. 782

Previous Ranking 2

Previous Photo References

Roll 31

Frame 17

312 E. Travis



2002-05 Re-evaluation

High Medium Low

Site ID No. 651
 Address 312 E. Travis
 Date 1890
 Stylistic Influence vernacular
 GCAD Hyperlink [R13364](#)
 Owner
 Historic District Yes Potential Historic District

Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes House has a rear circa 1920 addition (likely rear porch that was enclosed). Resource has two buildings to the rear (see #s 652 and 653).

1983 Historic Resources Survey

Previous Site No. 783

Previous Ranking 2

Previous Photo References

Roll 1

Frame 31

**Historic Review Board
Application Information**

Application Number: 14-55
Date: August 8, 2014
Address: 313 W. Austin
Owner: Estate of Deborah Howard
Applicant: Angela Moga
Rating: Medium
Proposed Modifications: Install metal carport.
Neighborhood Characteristics: The subject property is in the Historic District.
Staff Comments: The scope of the project justifies Board review.

General Notes:

The mandatory functions of the Board include the following:

(1) Removal, addition or modification of architectural detail. The distinguishing historic qualities or character of a building, structure, or site and its environment shall not be destroyed. Removal or modification of any historic material or distinctive architectural features may be accomplished upon issue of certificate of appropriateness; however, this should be avoided when possible. Architectural features include but are not limited to exterior wall materials, windows, railings, decorative woodwork, masonry, or stone elements.

(2) Paint color and application. Traditionally, the base colors of Fredericksburg's buildings have been soft muted shades of greens, blues, whites, and tans. In order to continue the historic integrity of the buildings in the district, these colors continue to be acceptable today, and do not require review or issuance of a certificate. The building official shall determine whether or not the proposed color is within the approved list of colors. Base colors such as vibrant or "hot" shades, dark deep shades, and black shades are not acceptable. If one wishes to use these colors, a certificate of appropriateness must be granted in advance of paint application. The painting of existing historic buildings composed of materials such as unpainted stone or unpainted masonry is prohibited.

(3) New construction in historic districts. The board will review all new construction plans within Historic Districts in order to ensure visual compatibility with the surrounding buildings and environment in relation to height, gross volume, proportion, design harmony and setback.

The advisory functions of the Board include the following:

- (1) The effect of the proposed change on the general historic, cultural, and architectural nature of the historic district or landmark.
- (2) The appropriateness of exterior architectural features which can be seen from a public street, alley, or walkway.
- (3) The general design, arrangement, texture, color, and material of the building, or structure, and the relation of such factors to similar features of buildings, or structures, in the district. This consideration shall not be the aesthetic appeal of the structure to the board nor the proposed remodeling, but rather its conformity to the general character of the particular historic area involved.
- (4) Conformance of signage to the general historic, cultural, and architectural character of the historic district or landmark.
- (5) The effects of the proposed change to the value of the historic district or landmark as an area of unique interest and character.
- (6) The general and specific Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, as issued by the secretary of the interior.
- (7) The importance of finding a way to meet the current needs of the property owner and the importance of approving plans that will be economically reasonable for the property owner to carry out.

Preservation Priority Rating. Three-tier rating system used in the 2002 *Fredericksburg Historic Resource Survey* to evaluate all properties within, and adjoining to, the City's Historic District. Ratings are based upon current determinations of architectural value and integrity and, if known, historical and cultural value, and may be altered from time to time as additional information is discovered or circumstances change.

HIGH rating. The most significant properties identified in the 2002 *Fredericksburg Historic Resource Survey*. These properties are considered to be outstanding, unique, or good examples of architecture, engineering, or design. Some are unique to the Fredericksburg area and are indicative of German-Texan vernacular forms and/or building techniques. Others are noteworthy examples of 19th and early 20th century architectural types, styles, and forms, erected using local building materials and construction technologies. Properties designated with a high rating are to be the most protected from alteration and demolition.

MEDIUM rating. Properties that may or may not be identified as architecturally significant on an individual basis, but are nonetheless valuable resources that add to the Historic District's overall character, and may be so ranked due to their or its proximity or contribution to the cultural, historic, architectural, or archeological character of the Historic District or surrounding properties. These properties may have been moderately altered or are typical examples of a common architectural style or form, but generally retain their historic integrity to a good or moderate degree. Properties designated with a medium rating shall be protected from demolition and where possible will be required or encouraged to maintain or improve architectural features.

LOW rating. Properties that minimally enhance the district's ability to convey a sense of time and place. These properties may be typical examples of more recent, common local building forms, architectural styles, or plan types; be examples of distinctive building forms, architectural styles, or plan types that have been significantly altered; lack the necessary age to meet the usual fifty (50) year threshold for possible National Register of Historic Places listing and do not appear to meet the National Register of Historic Places standard for exceptional significance for properties less than fifty (50) years of age, but which nevertheless may have relative value within the Historic District, meriting preservation. Properties or improvements with a low rating may be considered for relocation or demolition upon a determination by the Historic Review Board that the same can be accomplished with little or no consequence to the historical, cultural, architectural, or archeological character of the district or property.

14-55

Application for Certificate of Appropriateness

Application Date: 7/9/14 Application Complete: _____

Property Address: 313 W. Austin St., Fredericksburg, TX

Owner: Estate of Deborah Howard (Angela Howard POA) Phone No. 817-808-6531

Address: 10401 Bear Hollow Dr., Keller, TX 76248

Applicant: Angela Moga (POA) Phone No. 817-808-6531

Address: 10401 Bear Hollow, Keller, TX 76248 Fax No. _____

Description of External Alteration/Repair or Demolition: _____

Install 2 car Carport (see attached info)
(Structure 20x21 w/ Gable and both sides enclosed.)

Description of how the proposed change will be in character with the architectural or historic aspect of the structure or site: _____

Carport to be located a rear of property
approx 150+ft. from street.

Any circumstances or conditions concerning the property which may affect compliance with the ordinance: _____

None known

Drawing Sketch Date Submitted: _____ Historic Photograph (See attached)

Desired Starting Date: within 30 days from approval Desired Completion Date: (A.S.A.P.) within 60 days
SURVEY RATING: High Medium Low None info from approval.

RTHL: Estimated Date of Construction _____

APPLICANT SIGNATURE: Angela Moga
The Applicant certifies that he/she is the Owner or duly authorized Agent for the Owner of the Property

Building Official's Determination Date _____ Insignificant Significant
(Max 7 days)

S Joseph
Chairman's Determination Date 7/15/14 Insignificant Significant
(Max 7 days)

Meeting Date (40 days max. after complete application) _____ Notice to Applicant: _____

APPLICATION FEE: -\$10.00 plus Board Review, CERTIFICATE OF APPROPRIATENESS-\$40.00

RECEIVED
JUL 09 2014



14 Gauge Certified 20psf/110mph, 12 Gauge Certified 30psf/120mph

Certified price is based on concrete installations, for ground installations see options on reverse side.

Regular Style



Trimmed For Finished Appearance

STANDARD FEATURES INCLUDE:

14 gauge frame - 29g roofing - 5 Foot Legs - Bows 5' o.c.
Braces On All Center Bows - Braces On Corners For Added Strength

Boxed Eye Style

With horizontal roof



STANDARD FEATURES INCLUDE:

14 gauge - 29g roofing - 6 Foot Legs - Bows 5' o.c.
Braces On All Center Bows - Braces On Corners For Added Strength

Beckers



20 Year Limited* Warranty on Roofing Materials for 14 and 12 Gauge Units

M.H. Anchors available.

12x21	18x21	20x21	22x21	24x21
\$595	\$695	\$995	\$1195	\$1295
12x26	18x26	20x26	22x26	24x26
\$895	\$995	\$1195	\$1495	\$1595
12x31	18x31	20x31	22x31	24x31
\$1095	\$1195	\$1495	\$1795	\$1995
12x36	18x36	20x36	22x36	24x36
\$1295	\$1395	\$1795	\$2095	\$2295
12x41	18x41	20x41	22x41	24x41
\$1495	\$1695	\$2095	\$2495	\$2695

29 Gauge Steel Roof And Siding

12x21	18x21	20x21	22x21	24x21
\$695	\$795	\$1095	\$1295	\$1395
12x26	18x26	20x26	22x26	24x26
\$995	\$1095	\$1295	\$1595	\$1695
12x31	18x31	20x31	22x31	24x31
\$1195	\$1395	\$1595	\$1895	\$2145
12x36	18x36	20x36	22x36	24x36
\$1395	\$1595	\$1895	\$2195	\$2495
12x41	18x41	20x41	22x41	24x41
\$1695	\$1895	\$2295	\$2695	\$2895

Concrete Anchors included.

We Accept



Engineer Plans Available at additional Cost.

FREE Installation On Your Level Land

Vertical Roof Style

Boxed Eye style with Vertical Roof.



STANDARD FEATURES INCLUDE:

14 gauge frame - 29g roofing - 6 Foot Legs - Bows 5' o.c. - Braces On All Center Bows - Braces On Corners For Added Strength

12x21	18x21	20x21	22x21	24x21
\$995	\$1095	\$1295	\$1595	\$1695
12x26	18x26	20x26	22x26	24x26
\$1395	\$1495	\$1695	\$1995	\$2095
12x31	18x31	20x31	22x31	24x31
\$1695	\$1795	\$1995	\$2395	\$2595
12x36	18x36	20x36	22x36	24x36
\$1995	\$2095	\$2395	\$2795	\$2995
12x41	18x41	20x41	22x41	24x41
\$2295	\$2495	\$2695	\$3295	\$3495



NOTE: frame lengths are 20', 25', 30', etc., horizontal roofs have 6" overhang front and back, optional vertical roofs have no overhang front or back. Actual colors may vary slightly 12/11



Inventory of Properties

311 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 155
 Address 311 W. Austin
 Date 1940
 Stylistic Influence _____
 GCAD Hyperlink [R24880](#)
 Owner REINBACH, FELIX TIMOTHY & BARBARA QUINTERO
 Historic District Yes Historic District
 Assessment Typical example of a distinctive building plan that has suffered minor or no alterations.

Notes

1983 Historic Resources Survey	
Previous Site No.	_____
Previous Ranking	_____
Previous Photo References	
Roll	_____
Frame	_____

312 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 61
 Address 312 W. Austin
 Date 1880
 Stylistic Influence vernacular; Craftsman
 GCAD Hyperlink [R20631](#)
 Owner BRANDES, ROBERT R
 Historic District Yes Historic District
 Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations.

Notes Porch exhibits Craftsman influence, likely added c. 1920.

1983 Historic Resources Survey	
Previous Site No.	80
Previous Ranking	2
Previous Photo References	
Roll	24 24 25
Frame	36 37 3

313 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 154
 Address 313 W. Austin
 Date 1920
 Stylistic Influence Queen Anne
 GCAD Hyperlink [R22359](#)
 Owner HOWARD, DEBORAH L
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has undergone alterations or deterioration. Resource displays distinctive stylistic elements.

Notes Large rear addition

1983 Historic Resources Survey	
Previous Site No.	81
Previous Ranking	2
Previous Photo References	
Roll	18
Frame	24

315 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 153
 Address 315 W. Austin
 Date 1910
 Stylistic Influence vernacular
 GCAD Hyperlink [R19182](#)
 Owner JENSCHKE, ELENORA MISS
 Historic District Yes Historic District
 Assessment An outstanding, unique, or good representative example of architecture with only minor alterations or no alterations. Outstanding decorative features contribute to the resource's significance.

Notes

1983 Historic Resources Survey	
Previous Site No.	82
Previous Ranking	2
Previous Photo References	
Roll	18
Frame	25

The first part of the document discusses the importance of maintaining accurate records of all transactions. This includes not only sales and purchases but also any other financial activities that may occur. It is essential to ensure that all entries are properly documented and supported by appropriate evidence.

In addition, the document emphasizes the need for regular reconciliation of accounts. This process involves comparing the company's internal records with the bank statements to identify any discrepancies. By doing so, the company can ensure that its financial statements are accurate and reliable.

Finally, the document highlights the importance of maintaining up-to-date financial statements. These statements provide a clear and concise overview of the company's financial performance over a specific period. They are essential for making informed decisions and for communicating the company's financial health to stakeholders.

The second part of the document focuses on the importance of maintaining accurate records of all transactions. This includes not only sales and purchases but also any other financial activities that may occur. It is essential to ensure that all entries are properly documented and supported by appropriate evidence.

In addition, the document emphasizes the need for regular reconciliation of accounts. This process involves comparing the company's internal records with the bank statements to identify any discrepancies. By doing so, the company can ensure that its financial statements are accurate and reliable.

Finally, the document highlights the importance of maintaining up-to-date financial statements. These statements provide a clear and concise overview of the company's financial performance over a specific period. They are essential for making informed decisions and for communicating the company's financial health to stakeholders.

The third part of the document discusses the importance of maintaining accurate records of all transactions. This includes not only sales and purchases but also any other financial activities that may occur. It is essential to ensure that all entries are properly documented and supported by appropriate evidence.

**Historic Review Board
Application Information**

Application Number: 14-58
Date: August 8, 2014
Address: 202 S. Bowie
Owner: Melvin and DeLana Littleton
Applicant: H & H Vinyl Fencing
Rating: Medium
Proposed Modifications: Install 215' of vinyl fence.
Neighborhood Characteristics: The subject property is in the Historic District.
Staff Comments: The scope of the project justifies Board review.

General Notes:

The mandatory functions of the Board include the following:

- (1) Removal, addition or modification of architectural detail.** The distinguishing historic qualities or character of a building, structure, or site and its environment shall not be destroyed. Removal or modification of any historic material or distinctive architectural features may be accomplished upon issue of certificate of appropriateness; however, this should be avoided when possible. Architectural features include but are not limited to exterior wall materials, windows, railings, decorative woodwork, masonry, or stone elements.
- (2) Paint color and application.** Traditionally, the base colors of Fredericksburg's buildings have been soft muted shades of greens, blues, whites, and tans. In order to continue the historic integrity of the buildings in the district, these colors continue to be acceptable today, and do not require review or issuance of a certificate. The building official shall determine whether or not the proposed color is within the approved list of colors. Base colors such as vibrant or "hot" shades, dark deep shades, and black shades are not acceptable. If one wishes to use these colors, a certificate of appropriateness must be granted in advance of paint application. The painting of existing historic buildings composed of materials such as unpainted stone or unpainted masonry is prohibited.
- (3) New construction in historic districts.** The board will review all new construction plans within Historic Districts in order to ensure visual compatibility with the surrounding buildings and environment in relation to height, gross volume, proportion, design harmony and setback.

The advisory functions of the Board include the following:

- (1) The effect of the proposed change on the general historic, cultural, and architectural nature of the historic district or landmark.
- (2) The appropriateness of exterior architectural features which can be seen from a public street, alley, or walkway.
- (3) The general design, arrangement, texture, color, and material of the building, or structure, and the relation of such factors to similar features of buildings, or structures, in the district. This consideration shall not be the aesthetic appeal of the structure to the board nor the proposed remodeling, but rather its conformity to the general character of the particular historic area involved.
- (4) Conformance of signage to the general historic, cultural, and architectural character of the historic district or landmark.
- (5) The effects of the proposed change to the value of the historic district or landmark as an area of unique interest and character.
- (6) The general and specific Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, as issued by the secretary of the interior.
- (7) The importance of finding a way to meet the current needs of the property owner and the importance of approving plans that will be economically reasonable for the property owner to carry out.

Preservation Priority Rating. Three-tier rating system used in the 2002 *Fredericksburg Historic Resource Survey* to evaluate all properties within, and adjoining to, the City's Historic District. Ratings are based upon current determinations of architectural value and integrity and, if known, historical and cultural value, and may be altered from time to time as additional information is discovered or circumstances change.

HIGH rating. The most significant properties identified in the 2002 *Fredericksburg Historic Resource Survey*. These properties are considered to be outstanding, unique, or good examples of architecture, engineering, or design. Some are unique to the Fredericksburg area and are indicative of German-Texan vernacular forms and/or building techniques. Others are noteworthy examples of 19th and early 20th century architectural types, styles, and forms, erected using local building materials and construction technologies. Properties designated with a high rating are to be the most protected from alteration and demolition.

MEDIUM rating. Properties that may or may not be identified as architecturally significant on an individual basis, but are nonetheless valuable resources that add to the Historic District's overall character, and may be so ranked due to their or its proximity or contribution to the cultural, historic, architectural, or archeological character of the Historic District or surrounding properties. These properties may have been moderately altered or are typical examples of a common architectural style or form, but generally retain their historic integrity to a good or moderate degree. Properties designated with a medium rating shall be protected from demolition and where possible will be required or encouraged to maintain or improve architectural features.

LOW rating. Properties that minimally enhance the district's ability to convey a sense of time and place. These properties may be typical examples of more recent, common local building forms, architectural styles, or plan types; be examples of distinctive building forms, architectural styles, or plan types that have been significantly altered; lack the necessary age to meet the usual fifty (50) year threshold for possible National Register of Historic Places listing and do not appear to meet the National Register of Historic Places standard for exceptional significance for properties less than fifty (50) years of age, but which nevertheless may have relative value within the Historic District, meriting preservation. Properties or improvements with a low rating may be considered for relocation or demolition upon a determination by the Historic Review Board that the same can be accomplished with little or no consequence to the historical, cultural, architectural, or archeological character of the district or property.

14-58

Application for Certificate of Appropriateness

Application Date: 7.25.14 Application Complete: 7.25.14

Property Address: 202 South Bowie Street, Fredericksburg, TX 78624

Owner: Melvin and DeLana Littleton Phone No. 361.749.7333

Address: 420 E. Cotter Ave Port Aransas, TX 78373

Applicant: H&H Vinyl Fencing Littleton's on behalf of the Phone No. (830) 779-5050

Address: 3902 FM 775 La Vernia, Tx 78121

Description of External Alteration/Repair or Demolition: Remove approximately 215 linear feet of existing wood privacy fence and replace with approximately 215 linear feet of simulated stone vinyl fencing that will closely match the existing stone columns.

Description of how the proposed change will be in character with the architectural or historic aspect of the structure or site: Simulated stone will closely match in color and style the existing stone columns. Material comes with a 25-year to lifetime warranty, has a wind rating that meets Dade County Florida hurricane requirements, is fade & graffiti resistant, & is maintenance free.

Any circumstances or conditions concerning the property which may affect compliance with the ordinance: _____

None

Drawing Sketch Date Submitted: _____ Historic Photograph

Desired Starting Date: Summer 2014 Desired Completion Date: Summer 2014

SURVEY RATING: High Medium Low None

BTHL: Estimated Date of Construction _____

APPLICANT SIGNATURE: Theresa Pinnell

The Applicant certifies that he/she is the Owner or duly authorized Agent for the Owner of the Property

[Signature] Date 8/4/14 Insignificant Significant
Building Official's Determination (Max 7 days)




[Signature] Date 8/4/14 Insignificant Significant
Chairman's Determination (Max 7 days)

Meeting Date (40 days max. after complete application) _____ Notice to Applicant: _____


APPLICATION FEE: -\$10.00 plus Board Review; CERTIFICATE OF APPROPRIATENESS-\$20.00

26





Stunning Beauty - Lifetime Durability



Authentic - Granite-look walls and gates.

Durable - Molded of exceptionally tough polyethylene, reinforced with galvanized steel.

Impact - Superior strength - baseballs, golf balls, and rocks bounce off.

Temperature - Stable in hot and cold weather extremes. Withstands tests at -40° to $+140^{\circ}$ F.

Wind - Superior wind resistance, 110 mph sustained, 130 mph gusts, certified to Dade County, Florida hurricane requirements.

Fade Resistant - UV stabilized for a lifetime of vibrant color.



Sound Barrier - Blocks 98% of direct sound. Wood fences block 75%, concrete 100%.

Graffiti Resistant - Easily remove graffiti using a high powered pressure washer.


Maintenance Free - Install and enjoy.

Warranty - Manufacturer's Lifetime Warranty.

Made in the USA - out of recycled and new materials.



29



Inventory of Properties

302 N. Bowie



2002-05 Re-evaluation

High Medium Low

Site ID No. 767
 Address 302 N. Bowie
 Date 1950
 Stylistic Influence _____
 GCAD Hyperlink [R26746](#)
 Owner BIERSCHWALE, CREDIT & LENDING
 Historic District No Outside Historic District
 Assessment Typical example of a common building form, architectural style, or plan type that has suffered severe alterations or deterioration, resulting in a loss of historical integrity.

Notes

1983 Historic Resources Survey	
Previous Site No.	_____
Previous Ranking	_____
Previous Photo References	
Roll	_____
Frame	_____

108 ? S. Bowie



2002-05 Re-evaluation

High Medium Low

Site ID No. 773
 Address 108 ? S. Bowie
 Date _____
 Stylistic Influence _____
 GCAD Hyperlink _____
 Owner _____
 Historic District Yes Historic District
 Assessment Resource is an empty lot.

Notes

1983 Historic Resources Survey	
Previous Site No.	_____
Previous Ranking	_____
Previous Photo References	
Roll	_____
Frame	_____

109 S. Bowie



2002-05 Re-evaluation

High Medium Low

Site ID No. 533
 Address 109 S. Bowie
 Date 1950
 Stylistic Influence _____
 GCAD Hyperlink [R21134](#)
 Owner WALLACE, GRACE LORAINÉ
 Historic District Yes Historic District
 Assessment The resource's construction date fails to meet the age threshold for designation as a high or medium preservation priority.

Notes

1983 Historic Resources Survey	
Previous Site No.	_____
Previous Ranking	_____
Previous Photo References	
Roll	_____
Frame	_____

110 S. Bowie



2002-05 Re-evaluation

High Medium Low

Site ID No. 774
 Address 110 S. Bowie
 Date 1905
 Stylistic Influence Queen Anne
 GCAD Hyperlink [R28335](#)
 Owner LEE, RONALD E JR
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has suffered severe alterations or deterioration, resulting in a loss of historical integrity.

Notes Resource has a significant addition

1983 Historic Resources Survey	
Previous Site No.	_____
Previous Ranking	_____
Previous Photo References	
Roll	_____
Frame	_____

202 S. Bowie



2002-05 Re-evaluation

High Medium Low

Site ID No. 775
 Address 202 S. Bowie
 Date 1880
 Stylistic Influence vernacular
 GCAD Hyperlink [R58755](#)
 Owner COX, LINDA JANE P
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has undergone alterations or deterioration.

Notes Garage has been attached to the rear of this resource.

1983 Historic Resources Survey	
Previous Site No.	135
Previous Ranking	2
Previous Photo References	
Roll	22 22
Frame	31 32

**Historic Review Board
Application Information**

Application Number: 14-63

Date: August 8, 2014

Address: 522 W. Austin

Owner: Dr. John and Suzanne Shore

Applicant: Laughlin Homes & Restoration

Rating: Medium

Proposed Modifications: See attached.

Neighborhood Characteristics: The subject property is in the Historic District.

Staff Comments: The scope of the project justifies Board review.

General Notes:

The mandatory functions of the Board include the following:

- (1) Removal, addition or modification of architectural detail.** The distinguishing historic qualities or character of a building, structure, or site and its environment shall not be destroyed. Removal or modification of any historic material or distinctive architectural features may be accomplished upon issue of certificate of appropriateness; however, this should be avoided when possible. Architectural features include but are not limited to exterior wall materials, windows, railings, decorative woodwork, masonry, or stone elements.
- (2) Paint color and application.** Traditionally, the base colors of Fredericksburg's buildings have been soft muted shades of greens, blues, whites, and tans. In order to continue the historic integrity of the buildings in the district, these colors continue to be acceptable today, and do not require review or issuance of a certificate. The building official shall determine whether or not the proposed color is within the approved list of colors. Base colors such as vibrant or "hot" shades, dark deep shades, and black shades are not acceptable. If one wishes to use these colors, a certificate of appropriateness must be granted in advance of paint application. The painting of existing historic buildings composed of materials such as unpainted stone or unpainted masonry is prohibited.
- (3) New construction in historic districts.** The board will review all new construction plans within Historic Districts in order to ensure visual compatibility with the surrounding buildings and environment in relation to height, gross volume, proportion, design harmony and setback.

The advisory functions of the Board include the following:

- (1) The effect of the proposed change on the general historic, cultural, and architectural nature of the historic district or landmark.
- (2) The appropriateness of exterior architectural features which can be seen from a public street, alley, or walkway.
- (3) The general design, arrangement, texture, color, and material of the building, or structure, and the relation of such factors to similar features of buildings, or structures, in the district. This consideration shall not be the aesthetic appeal of the structure to the board nor the proposed remodeling, but rather its conformity to the general character of the particular historic area involved.
- (4) Conformance of signage to the general historic, cultural, and architectural character of the historic district or landmark.
- (5) The effects of the proposed change to the value of the historic district or landmark as an area of unique interest and character.
- (6) The general and specific Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, as issued by the secretary of the interior.
- (7) The importance of finding a way to meet the current needs of the property owner and the importance of approving plans that will be economically reasonable for the property owner to carry out.

Preservation Priority Rating. Three-tier rating system used in the 2002 *Fredericksburg Historic Resource Survey* to evaluate all properties within, and adjoining to, the City's Historic District. Ratings are based upon current determinations of architectural value and integrity and, if known, historical and cultural value, and may be altered from time to time as additional information is discovered or circumstances change.

HIGH rating. The most significant properties identified in the 2002 *Fredericksburg Historic Resource Survey*. These properties are considered to be outstanding, unique, or good examples of architecture, engineering, or design. Some are unique to the Fredericksburg area and are indicative of German-Texan vernacular forms and/or building techniques. Others are noteworthy examples of 19th and early 20th century architectural types, styles, and forms, erected using local building materials and construction technologies. Properties designated with a high rating are to be the most protected from alteration and demolition.

MEDIUM rating. Properties that may or may not be identified as architecturally significant on an individual basis, but are nonetheless valuable resources that add to the Historic District's overall character, and may be so ranked due to their or its proximity or contribution to the cultural, historic, architectural, or archeological character of the Historic District or surrounding properties. These properties may have been moderately altered or are typical examples of a common architectural style or form, but generally retain their historic integrity to a good or moderate degree. Properties designated with a medium rating shall be protected from demolition and where possible will be required or encouraged to maintain or improve architectural features.

LOW rating. Properties that minimally enhance the district's ability to convey a sense of time and place. These properties may be typical examples of more recent, common local building forms, architectural styles, or plan types; be examples of distinctive building forms, architectural styles, or plan types that have been significantly altered; lack the necessary age to meet the usual fifty (50) year threshold for possible National Register of Historic Places listing and do not appear to meet the National Register of Historic Places standard for exceptional significance for properties less than fifty (50) years of age, but which nevertheless may have relative value within the Historic District, meriting preservation. Properties or improvements with a low rating may be considered for relocation or demolition upon a determination by the Historic Review Board that the same can be accomplished with little or no consequence to the historical, cultural, architectural, or archeological character of the district or property.

14-63

Application for Certificate of Appropriateness

Application Date: 7/28/2014 Application Complete: _____

Property Address: 522 W. Austin, Fredericksburg, TX 78624, Corner of North Bowie and West Austin

Legal Description: Town Lots No. 43AR-1R & 43BR-11R, Corner of N. Bowie and W. Austin

Owner: Dr. John & Suzanne Shore Phone No. 830-997-4974

Address: West Austin Street

Applicant: Laughlin Homes & Restoration Phone No. 830-997-4974

Address: 616 W. Main

Description of External Alteration/Repair or Demolition: New home construction addition to existing structure. Existing structure previously submitted and approved for move with Historic Review Board.

Description of how the proposed change will be in character with the architectural or historic aspect of the structure or site: _____

See Attached Plans

Any circumstances or conditions concerning the property which may affect compliance with the ordinance: _____

None

Drawing Sketch Date Submitted: _____ Historic Photograph

Desired Starting Date: _____ Desired Completion Date: _____

SURVEY RATING: High Medium Low None
 RTFL: Estimated Date of Construction _____

APPLICANT SIGNATURE:

The Applicant certifies that he/she is the Owner or duly authorized Agent for the Owner of the Property

[Signature] Date 8/4/14 Insignificant Significant
Building Official's Determination (Max 7 days)

[Signature] Date 8/4/14 Insignificant Significant
Chairman's Determination (Max 7 days)

Meeting Date (40 days max. after complete application) _____ Notice to Applicant: _____


APPLICATION FEE:-\$10.00 plus Board Review; CERTIFICATE OF APPROPRIATENESS-\$20.00

Property Line - 106.72'

10' Setback

Property Line - 147.95'

Property Line - 147.21'



Existing Structure

Property Line - 105.17'

West Austin Street



SQUARE FOOTAGE

0.00 96 sq. ft. - conditioned space - 695.25 sq. ft. - garage
4,376.21 sq. ft. - gross - 1,200.83 sq. ft. covered parking
5,655.94 sq. ft. - TOTAL PROJECT GROSS UNDER COVERED ROOF BUILDING AREA




SITE PLAN


Shore - Fredericksburg - Texas

SCALE: 1" = 10'-0"

36



Existing Structure



Upstairs




GROUND FLOOR
 Shore Residence - Fredericksburg, Texas
 SCALE 1/8\"/>

JULY 12, 2014



UPPER FLOOR
 Shore Residence - Fredericksburg, Texas
 SCALE 1/8\"/>

JULY 12, 2014




38

NORTH BOWIE - STREET ELEVATION
 Shore Residence - Fredericksburg, Texas

July 12, 2014






WEST AUSTIN - STREET ELEVATION
 Shore Residence - Fredericksburg, Texas


July 12, 2014

SCALE: 1/8" = 1'-0"



39

40




STANDING SEAM METAL ROOF - PAINT GRIP
WOOD SHAKES
STONE VENEER
WOOD SIDING


REAR ELEVATION

Shore Residence - Fredericksburg, Texas

July 12, 2014

SCALE: 1/8" = 1'-0"






CROSS SECTION - COURTYARD ELEVATION


Shore Residence - Fredericksburg, Texas

July 12, 2014

SCALE: 1/8" = 1'-0"



41




SIDE ELEVATION - MASTER

Shore Residence - Fredericksburg, Texas

July 12, 2014

SCALE: 1/8" = 1'-0"



Inventory of Properties

522 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 45
 Address 522 W. Austin
 Date 1890
 Stylistic Influence vernacular
 GCAD Hyperlink
 Owner
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has undergone alterations or deterioration.

Notes Building's exterior walls have been reclad with asbestos shingles.

1983 Historic Resources Survey

Previous Site No. 105
 Previous Ranking 2
 Previous Photo References
 Roll 24
 Frame 15

524 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 44
 Address 524 W. Austin
 Date 1920
 Stylistic Influence Craftsman
 GCAD Hyperlink [R14356](#)
 Owner CRENWELGE, EUGENE G MRS
 Historic District Yes Historic District
 Assessment Typical example of a distinctive building plan that has suffered minor or no alterations. Resource displays distinctive stylistic elements.

Notes Building's exterior walls have been reclad with asbestos shingles.

1983 Historic Resources Survey

Previous Site No. 106
 Previous Ranking 4
 Previous Photo References
 Roll 24
 Frame 14

602 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 43
 Address 602 W. Austin
 Date 1875
 Stylistic Influence vernacular
 GCAD Hyperlink [R26256](#)
 Owner WENDEL, MARTIN CONRAD
 Historic District Yes Historic District
 Assessment Example of a distinctive building type or architectural style that has undergone alterations or deterioration. Despite alterations or deterioration, resource retains much of its original form and character.

Notes Anton Kunz Home. Front façade stone has been repointed with cement. Resource has rear and side wood-frame additions w/asbestos shingle siding.

1983 Historic Resources Survey

Previous Site No. 107
 Previous Ranking 1
 Previous Photo References
 Roll 24 24 24
 Frame 9 10 11

603 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 139
 Address 603 W. Austin
 Date 1960
 Stylistic Influence
 GCAD Hyperlink [R24808](#)
 Owner REEH, THOMAS WAYNE & MICHAEL E
 Historic District Yes Historic District
 Assessment The resource's construction date fails to meet the age threshold for designation as a high or medium preservation priority.

Notes

1983 Historic Resources Survey

Previous Site No. _____
 Previous Ranking _____
 Previous Photo References
 Roll _____
 Frame _____

604 W. Austin



2002-05 Re-evaluation

High Medium Low

Site ID No. 42
 Address 604 W. Austin
 Date 1925
 Stylistic Influence
 GCAD Hyperlink [R26254](#)
 Owner WENDEL, MARTIN CONRAD
 Historic District Yes Historic District
 Assessment Example of a distinctive building plan that has undergone alterations or deterioration.

Notes Original porch posts replaced w/metal columns.

1983 Historic Resources Survey

Previous Site No. _____
 Previous Ranking _____
 Previous Photo References
 Roll _____
 Frame _____